

# Chile Earthquake – 2/27/2010

## Implications for U.S. Building Codes and Standards

John Wallace, EERI LFE Team Member  
John Hooper, ASCE SEI Team Leader

San Francisco – June 2, 2010



# Overview

- Background
  - Ground Motions
  - Response Spectra
  - Code Spectra
- Places Visited
  - Concepción
  - Viña del Mar
  - Santiago
  - Talca
- US Code Implications

O'Higgins 241




# U de Chile: Ground Motion Array





# Santiago: $A_{g,max} = 0.562g$

REGISTRO RENADIC: ESTACION: CRS MAIPU SANTIAGO / P. SOTO R. BOROSCHEK  
UNIVERSIDAD DE CHILE RED NACIONAL DE ACELEROGRAFOS  
( Frec. Banda: 0.06 - 40 Hz)



# Santiago Hospital: $A_{g,max} = 0.265g$





**Figura 15 Comparación Espectro de Diseño Norma Chilena NCh433 – Estación Hospital Sotero del Río RM.**

ESPECTRO de RESPUESTA  $\beta = 5\%$   
REGISTRO: RENADIC: ESTACION: HOSP CURICO / P. SOTO R. BOROSCHEK  
UNIVERSIDAD DE CHILE RED NACIONAL DE ACELEROGRAFOS  
(Banda Frec: 0.055 - 40 Hz)




Figura 18 Comparación Espectro de Diseño Norma Chilena NCh433 – Estación Hospital Curico.

ESPECTRO de RESPUESTA  $\beta = 5\%$   
REGISTRO: RENADIC: ESTACION: CRS MAIPU SANTIAGO / P. SOTO R. BOROSCHEK  
UNIVERSIDAD DE CHILE RED NACIONAL DE ACELEROGRAFOS  
(Banda Frec: 0.06 - 40 Hz)






Figura 9 Comparación Espectro de Diseño Norma Chilena NCh433 – Estación CRS MAIPU RM. (Ver Nota General)


# M7.8 1985 Earthquake; 2% Damped



# Viña del Mar: Acceleration Spectra



# Viña del Mar: Displacement Spectra



# RC Buildings

- Team effort
- Topics focused
  - Buildings as examples
  - ACI 318-08
  - ASCE 7-05
  - ASCE 41-06
  - Performance-based design



# Catastro por comuna

Tras el fuerte sismo, las municipalidades de la Región Metropolitana han iniciado un catastro de sus construcciones para determinar los daños. Hasta el momento, más de 23 presentan daños severos.




# Santiago

## Primary sources

Peers in Chile


J. Moehle

Others



# Concepción: 11+ Modern Buildings

- Caupolican 518
- Los Carrera 1535
- Salas 1343, Torre A
- O'Higgins 241
- Lincoyan 440
- Freire 1165
- Rozas 1145
- Padre Hurtado 776
- Obispo Salas
- Bosquemar (San Pedro)
- Olas (San Pedro)



# Concepción: 11+ Modern Buildings



# Viña del Mar: 11 Red, 4+ others



# Discussion Topics

In no particular order...

And not necessarily limited to a single research project per topic...

# 1. Wall Axial Stress

Toledo – Viña del Mar




Antigona – Viña del Mar



Macul - Santiago




# 1. Wall Axial Stress




Unit Weight: 150 to 200 psf

# 1. Wall Axial Stress

- Impact of lower wall area to floor area ratios
  - 1985 (6% - 3% in each direction; Festival)
  - 2010 (2% - 1% in each direction)



# 1. Wall Axial Stress



# 1. Wall Axial Stress – Limits?

- UBC 97 S19.21.6.6.3
  - Walls and portions of walls with  $P_u > 0.35P_o$  shall not be considered to contribute to the calculated strength of the structure...
- LA Tall Buildings 2008 – Supplement #1
  - Frame members subjected to high axial stress
  - Column axial load under governing load combinations (average of the values from the seven or more ground motion pairs per Section 3.4. of 2008 LATBSDC) shall not exceed  $0.40f'_cA_g$

## 2. Wall Boundary Detailing

- Chile Code NCh 433.Of96 is based on ACI 318-95 with important exceptions
- Chapter 21 – Section 21.6.6
  - “Special Boundary Elements”
  - Transverse reinforcement at wall boundary to confine the concrete and restrain rebar buckling is not required based on the good performance of wall buildings in Viña del Mar in the 1985 earthquake.
- ACI 318-02 added modified requirements for required transverse reinforcement at splices

## 2. Wall Boundary Detailing



Large spacing – 20cm [8"]  
90 degree hooks

## 2. Boundary Detailing

- Special RC Walls
  - Displacement-based approach introduced into ACI 318-99; Trigger for special boundary elements based on DBE.
    - Should it be based on MCE [or alternative approach for NRHA]?
    - Modeling assumptions that produce design displacement
  - Minimum transverse reinforcement ( $s < 8''$ ) for cases where special boundary elements are not required if  $\rho > 400/f_y$ ;
    - Should we always confine the hinge region?
    - Above the hinge?

## 2. Boundary Detailing

- Ordinary RC walls
  - For MCE, and maybe even a DBE, are we designing walls that are likely to experience damage similar to what was observed in Chile?
    - Repair cost, disruption cost? Relocation cost?
    - Require some level of detailing for all walls in certain regions
  - Maybe we need to rethink our expectations for code-compliant buildings?




## 2. Boundary Detailing – Revise?

- Study a statistically significant sample of buildings in Chile:
  - Using common modeling approaches and code procedures to assess if observed damage is consistent with expectations
  - With a focus on both Special Walls and Ordinary Walls

### 3. Wall Vertical Reinforcement

- Lightly-reinforced and poorly-detailed walls



# 3. Wall Vertical Reinforcement

Lightly-reinforced walls



### 3. Wall Vertical Reinforcement

- Lightly-reinforced or poorly-detailed walls
  - Tension fracture [lightly-reinforced]
  - Tensile yielding, followed by buckling and concrete spalling, followed by fracture [poorly-detailed]
  - Concentration of nonlinear deformation over short length or at a single crack
  - Potential for unzipping of wall



# 3. Wall Vertical Reinforcement



# 3. Wall Vertical Reinforcement

- “Unconfined Splices”



# 4. Configuration Issues




# 4. Configuration Issues - Vertical



## 4. Configuration Issues – Studies?




- Chilean code does not have specific provisions that limit irregularities
  - NCh 433.Of96 5.5.2.4: At levels where there is a stiffness discontinuity in the resisting planes or other vertical substructures, it must be verified that the diaphragm will be capable of redistributing the forces.
- ASCE 7-05
  - Table 12.3-1 Horizontal Structural Irregularities
  - Table 12.3-2 Vertical Structural Irregularities
- Detailed study of buildings with various degrees of irregularities to assess ASCE provisions

# 5. Building Collapse I



LA Tall  
Buildings  
Presentation


# 5. Building Collapse I



# 5. Building Collapse I

- Detailed study of this building to ascertain:
  - If our best analysis tools are capable of predicting this result,
  - What were the key attributes that contributed to the collapse, and
  - Whether the building satisfies U.S. codes and, if not, to what extent does the lack of compliance identify potential problems.

# 6. Building Collapse II



# 6. Building Collapse II



Photo: P. Bonelli, U Técnica Santa Maria


# 6. Building Collapse II

- Detailed study of several buildings that did not collapse to:
  - Ascertain if our best analysis tools are capable of predicting this result,
  - Determine key modeling limitations/shortcomings,
  - Assess uncertainties associated with modeling parameters, and how they impact the collapse assessment,
  - Determine if the building satisfies U.S. codes and, if not, to what extent does the lack of compliance identify potential problems,
  - Proximity of similar buildings without damage

# Bosque Mar – San Pedro – 23 stories



# 7. Rehabilitation: Hanga Roa 1985



# 7. Rehabilitation: Hanga Roa 2010



# 7. Rehabilitation: Festival (Viña)

14 Stories



# 7. Rehabilitation: Festival 2010

Post-1985 study indicated shear stress of about  $1.3V_n$

Demands (spectral) similar for 1985 and 2010 earthquake






# 7. Rehabilitation: Festival



-1 Level Parking

# 7. Rehabilitation: Festival



1<sup>st</sup> Level corridor walls @ Axis 9


# 8. Instrumented Buildings

- In support of modeling studies



# 8. Instrumented Buildings

- In support of modeling studies



## Instrumented floors:

- Parking Level (-1) : 1 triaxial sensor
- 2<sup>nd</sup> floor : 3 triaxial sensors
- 9<sup>th</sup> floor : 3 uniaxial sensors
- Roof : 3 uniaxial sensors

# 9. Ground Motion - Directionality

- Viña del Mar:
  - Damage generally more concentrated in buildings with short plan dimension in the north-south direction [preliminary spectra – roughly same demands NS & EW, and wrt 1985]
- Concepción:
  - Damage generally more concentrated in buildings with short plan dimension in the east-west direction [Alto Rio, Centro Mayor, Salas 1343A]
- Study of similar buildings with different orientations [Salas 1343, Concepción]

# 10. Slab coupling [Gravity Elements]

- Impact of slab coupling on system responses



# Special Thanks

- Prof. Rodolfo Saragoni, U de Chile
- Prof. Leonardo Massone, U de Chile
- Prof. Juan Carlos de la Llera, U Católica de Chile
- Prof. Rafael Riddell, U Católica de Chile
- Prof. Patricio Bonelli, U Técnica Santa Maria
- Prof. Jack Moehle, UC Berkeley, EERI Team Leader
- Alvaro Celestino, Degenkolb Los Angeles, EERI
- Claudio Frings, Juan Pablo Herranz, Benjamin Westenenk, Juan Jose Besa, U de Católica
- Arturo Millán, U Técnica Santa Maria